

SERVICE BULLETIN

Reference number:	SB-19-1110	Issued: 24 May, 2018
Subject:	AMDS II Update Procedure	
Model(s):	All Vehicles	
VIN Range:	All	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Bulletin

The Aston Martin Diagnostic System (AMDS II) does a check for software updates each time the programme is launched. You must do the procedure that follows when software updates are downloaded.

Workshop Procedure

CAUTION: CONNECT THE AMDS TO AN ELECTRICAL SUPPLY WHEN YOU DO THE PROCEDURE THAT FOLLOWS. IF THE AMDS BATTERY BECOMES DISCHARGED DURING THE SOFTWARE UPDATE, THE UPDATE CAN FAIL.

1. If an update is available, the "Application Install – Security Warning" window will appear (refer to Figure 1). Click "Install".




Figure 1

2. The update will download from the AMDS server (refer to Figure 2).




Figure 2

3. If the “Windows protected your PC” window appears, click on the “[More info](#)” hyperlink (refer to Figure 3).

Note: Do not click the “Don’t run” button. If you do, AMDSII will not function correctly.




Figure 3

4. Click the “Run anyway” button (refer to Figure 4).




Figure 4

5. AMDSII will then open with the update successfully installed (refer to Figure 5).




Figure 5

Warranty Data**Procedure and Labour Time**

Not applicable.

If you have any questions related to this Service Bulletin, please contact: Aston Martin Technical Services
on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
Or contact your After Sales Manager.

The English version of this Service Bulletin is written in
Simplified Technical English to ASD-STE100™.