



GROUP
ENG

MODEL
2017MY
Cadenza (YG)

NUMBER
171

DATE
August 2017

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: ELECTRIC THERMOSTAT
ASSEMBLY REPLACEMENT (SA299)

This bulletin provides the procedure to replace the electric thermostat assembly on some 2017MY Cadenza (YG) vehicles, produced from June 2, 2016 through December 28, 2016, which may exhibit a Malfunction Indicator Light (MIL) illuminated with one or more DTCs as listed below. To correct or prevent this concern, follow the procedure outlined in this bulletin to replace the electric thermostat. Before conducting the procedure, verify that the vehicle is included in the affected VIN list.

P0597: Thermostat Heater Control Circuit

P0598: Thermostat Heater Control Circuit

P0599: Thermostat Heater Control Circuit High

P0128: Coolant Temperature Below Threshold

**ENG171/SA299
CLOSED
REFER TO TSB
ENG188/SA346**



* NOTICE

A Service Action is a repair procedure that requires customer notification that is performed during the warranty period. If a customer is requesting to perform this repair outside the warranty period will require a Warranty Authorization from KMA.

Repair status for a VIN is located on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA299.

File Under: <Engine>

Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair