

<b>Reference</b>	SSM73846
<b>Models</b>	F-TYPE / X152
<b>Title</b>	2018 MY Anti Lock Braking (ABS) software missing after an update is performed.
<b>Category</b>	Chassis
<b>Last modified</b>	09-Apr-2018 00:00:00
<b>Symptom</b>	301000 Service Brake System
<b>Content</b>	<p><b><u>Issue:</u></b> The Anti-Lock Brake System (ABS) module software is no longer present within the module after an attempt to update the software with Pathfinder.</p> <p><b><u>Cause:</u></b> The cause of the concern is currently under investigation. At this stage we suspect that the software bootloader is corrupt.</p> <p><b><u>Action:</u></b> Escalate the Technical Assistance (TA) to Global Diagnostic Support (GDS). A WebEx session will be arranged to recover the software within the ABS module.</p> <p><b>DO NOT REPLACE THE MODULE</b></p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>