

<b>Reference</b>	SSM73844
<b>Models</b>	E-PACE / X540 F-PACE / X761 F-TYPE / X152 XE / X760 XF / X260
<b>Title</b>	New Supplementary Restraints System(SRS) firing circuit repair process
<b>Category</b>	Electrical
<b>Last modified</b>	10-Apr-2018 00:00:00
<b>Symptom</b>	203000 Basic Electrical
<b>Content</b>	<p><b><u>For Information Only.</u></b></p> <p>In the event that an SRS firing circuit is found to be damaged, please refer to SCN JLRP00128 and TOPIx (workshop manual section 418-02 - Description and Operation – Diagnosis and Testing) for the updated wiring repair standard and guidelines.</p> <p>Jaguar Land Rover has released a kit of parts to allow lower level repairs of all SRS firing circuits.</p> <p><b><u>Note: Only applicable to these vehicles</u></b> E Pace F Pace XE XF F Type</p> <p><b><u>Part number</u></b> T2H36530</p> <p>Technicians - Please rate this SSM and provide comments so that future communications can be improved.</p> <p>1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.</p> <p>3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.</p> <p>5 = Excellent – All required information provided to resolve the customer concern.</p>

