

MIL On with DTC P2271?

AFFECTED VEHICLES

Year	Model	Trim
2006-07	Accord L4	VP, SE, LX, EX, EX-L
2005-06	CR-V	All
2007-08	Element	All
2006-08	S2000	All

Is the MIL on with DTC P2271 (secondary HO2S [sensor 2] circuit signal stuck rich)? What's likely causing this is the PCM is misinterpreting the A/F sensor (sensor 1) signals, causing the PCM to think that sensor 2 is stuck rich.

To fix this issue, replace both sensors.