

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: LACK OF POWER UNDER HEAVY LOAD, NO WARNING LIGHTS OR DTCs	Service Alert No.: SA-024/18
	Last Issued: 05/03/2018

APPLICABLE MODEL(S)/VINS

2016-2018 CX-3	2016-2018 MX-5
2013-2018 CX-5	2013-2018 Mazda3
2016-2018 CX-9	2014-2018 Mazda6

DESCRIPTION

Some customers may complain of a lack of power under heavy load without any warning lights or DTCs. This concern may be due to a loose or detached hood weatherstrip, which can cause a blockage or restriction in the air intake system.

(Hood Weatherstrip Location Shown Below, Correctly installed)



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

(Hood Weatherstrip Shown Below, Loose / Detached From Hood)



To correct this concern, reattach the weatherstrip or replace it with a new one if it is damaged.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.