

Reference	SSM73845
Models	Discovery / L462 Discovery Sport / L550 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494 Range Rover Velar / L560
Title	New supplementary Restraints System(SRS) firing circuit repair process
Category	Electrical
Last modified	10-Apr-2018 00:00:00
Symptom	203000 Basic Electrical

Content**For Information Only**

In the event that a SRS firing circuit is found to be damaged, please refer to SCN JLRP00128 and TOPIx (workshop manual section 418-02 - Description and Operation – Diagnosis and Testing) for the updated wiring repair standard and guidelines.

Jaguar Land Rover has released a kit of parts to allow lower level repairs of all SRS firing circuits.

Note : Only applicable to these vehicles

Range Rover
Range Rover Sport
Velar
Evoque
Discovery Sport
Discovery(L462)

Part number

LR110730

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.