



LTB01100NAS2

# TECHNICAL BULLETIN

11 APR 2018

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

## INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

Changes are highlighted in blue

## SECTION:

501-08: Exterior Trim and Ornamentation

## SUBJECT/CONCERN:

Roof Panel Moulding Loose

## AFFECTED VEHICLE RANGE:

**MODEL:****MODEL YEAR:****VIN:****ASSEMBLY PLANT:**

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Discovery (LR)	2017	000532-020448	Solihull

## MARKETS:

NORTH AMERICA

## CONDITION SUMMARY:

### SITUATION:

A roof panel molding may be loose and/or wind noise may be evident from the upper windshield/roof panel area.

### CAUSE:

This may be caused by poor fit of the corresponding parts.

### ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

## PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
LR114296	Roof Panel Moulding Clips - Rear	10
LR114293	Roof Panel Moulding Clips - Front right	1
LR114295	Roof Panel Moulding Clips - Front left	1

## TOOLS:

Refer to Workshop Manual for any required special tools.

## WARRANTY:

### NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Roof Panel Moulding - Both - Renew	76.43.68.01	0.2	12	LR083015

### NOTE:

Normal Warranty procedures apply.

### WORKSHOP PROCEDURE:

- 1 Replace the roof panel left and right mouldings (see TOPIx Workshop Manual section 501-08: Exterior Trim and Ornamentation - Roof Moulding).