

## HONDA Tech Line Summary Article

May 2018 ATS 180501 Version 1

## **Rumbling from the Driver's Door Speaker**

## **AFFECTED VEHICLES**

Year	Model	Trim
2018	Odyssey	Elite

Are you hearing a rumbling from the driver's door speaker that sounds like driving on a shoulder rumble strip? We're aware of this issue and have it under investigation.

So far, we know this noise happens around 1,500 rpm with the vehicle in valve pause, is not dependent on vehicle speed, and varies in intensity depending on how long you're in ANC mode.

We've also found the root cause and have a solution in the works. Until it's available, don't replace any parts for this issue. And most importantly, don't unplug the ANC unit; you'll just cause more issues.