

[Next Unread Message](#)**View Message**

Sent on	05	10	2018	Expires on	05	24	2018
From	Parts and Service Division						
Subject	Request for Parts: 2015-2018 TLX 2WD MIL On with DTC U129D Stored						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
 From: Technical Research & Support Group
 RE: Request for Parts: 2015-2018 TLX 2WD MIL On with DTC U129D Stored

**This message is solely directed to Acura dealership personnel; please handle accordingly.
 Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2015-2018 TLX 2WDs with a client complaint of Malfunction Indicator Lamp (MIL) on with DTC U129D (Lost Communication with the Precision All Wheel Steer Control Unit) stored. Client may experience limited speed of up to 50mph or the steering wheel not centered. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Vehicle must be 2WD.
2. After confirming the DTC U129D, one of the following DTCs must also be confirmed.
 C1600-94 (Precision All Wheel Steer System Unexpected Operation)
 C1621-13 (Left-Rear Precision All Wheel Steer Actuator Circuit Open)
 C1611-13 (Right-Rear Precision All Wheel Steer Actuator Circuit Open)
3. Vehicle must be in failsafe mode (limited speed of up to 50mph)
4. DO NOT clear the DTC out of the RTC (Rear Toe Control) control unit.
5. No repair has been attempted for this issue.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.