

HONDA Tech Line Summary Article

June 2018 ATS 180602 Version 1

Rubbing Noise While Driving at Low Speed

AFFECTED VEHICLES

Year	Model	Trim
2016-17	Accord	Sport

Tech Line has been getting calls about a rubbing noise while driving at low speed. We're working with our field engineers to understand the issue and are in the process of calling in parts.

For now, if you get any vehicles in for this, as a temporary fix, just clean and lube the tire bead and balance the tires.