

*** * TECHNICAL INFORMATION NOTICE * ***

DATE: June 7, 2018
TO: Mitsubishi Motors US & Puerto Rico Dealer Service and Parts Managers
RE: Engine ECU Software Update in TSB-18-13-001 & TSB-18-13-002 Addresses Both DTC P0068 & P061A
TIN NO. TIN-18-13-002

.....

AFFECTED VEHICLES: 2018 Eclipse Cross

PURPOSE

An Engine ECU software update will be available soon to address MFI DTCs P0068 and P061A that have been improperly set. When reprogramming the Engine ECU software to resolve DTC P0068 or P061A, be sure to first check the software part number as described in TSB-18-13-001 and TSB-18-13-002.

If the Software Part Number listed is 1860D11603 or higher, then the software update for P0068 and P061A has been completed. There is no need to complete the procedure in both TSBs, as software level 1860D11603 addresses both issues.

