



SERVICE ACTION N176: DISTANCE TO SERVICE MESSAGE NOT CORRECTLY DISPLAYED

SERVICE BULLETIN

07-MAY-18

NO.: SGI18-14
(ISSUE 2)

SEC.: GENERAL
INFORMATION

MKT.: CAN / USA

CHANGES ARE HIGHLIGHTED IN BLUE

DESCRIPTION OF ISSUE

A potential issue has been identified on a limited number of Land Rover vehicles within the listed Affected Vehicle Range where the Instrument Cluster 'Distance to Service' message displays but then the kilometers/miles changes to dashes, resulting in customers seeing the message 'Service required in ---- -kilometers/miles'.

AFFECTED VEHICLE RANGE

Range Rover Sport (L494)

Model Year: 2017

VIN: 112609-166288; 664289-691414

Range Rover (L405)

Model Year: 2017

VIN: 311572-366599

Visit the Land Rover InfoTrail website for a list of affected unsold vehicles (as of 21 March 2018).

SERVICE PROGRAM / REWORK ACTION

Retailers will update the Instrument Cluster with the latest software. There will be no charge to owners for this action under this program.

ACTION TO BE TAKEN

Use the Jaguar Land Rover claims submission system to ensure that the vehicle is affected by this program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin N176NAS, *Service Action: Distance to Service Message Not Correctly Displayed*, for detailed repair instructions.

PARTS

No parts required.

TOOLS

Refer to Technical Bulletin noted above for any required tools.

WARRANTY

NOTE: use the Jaguar Land Rover claims submission system to make sure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that all outstanding Recall and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to the Jaguar Land Rover claims submission system to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the 31 March 2020 closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS / SUNDRY CODE	QTY. / VALUE
N176	B	Instrument Cluster Update	86.91.25	0.20	-	-
N176	C	Instrument Cluster Update	86.91.25	0.20	-	-
		Drive in/drive out	02.02.02	0.20	-	-

Normal Warranty policies and procedures apply.