ATTENTION:


GENERAL MANAGER

PARTS MANAGER

CLAIMS PERSONNEL

SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



© 2018 Subaru of America, Inc. All rights reserved.

(

SUBARU.

QUALITY DRIVEN® SERVICE

SERVICE INFORMATION BULLETIN

APPLICABILITY: 2017MY Impreza 5-Door Models

NOMBER

NUMBER: 12-245-18

2018MY Crosstrek

DATE: 06/11/18

SUBJECT: Rear Gate Trim Panels- Design Change

INTRODUCTION:

This Service Information bulletin announces a design change to the rear gate trim panels on the models specified above. The change was made to the areas of the panels where they fit together to improve production line efficiency.

PRODUCTION CHANGE INFORMATION:

The new trim panels were incorporated into production starting with the following VINs:

• Impreza 5-Door Models: J*737664

Crosstrek: J*200121

PART INFORMATION:

Description	Part Number	Applicability
TRIM PNL ASSY R G LWR	94320FL030VH	
TRIM PNL ASSY R G SDR	94330FL060VH	Crosstrek
TRIM PNL ASSY R G SDL	94330FL070VH	
TRIM PNL ASSY R G LWR	94320FL02AVH	
TRIM PNL ASSY R G SDR	94330FL04AVH	Impreza 5-Door
TRIM PNL ASSY R G SDL	94330FL05AVH	

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.


Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Bulletin Number: 12-245-18; Date 06/11/18

Page 1 of 2



SERVICE PROCEDURE / INFORMATION:

NOTE: These new parts are not interchangeable with original (old-style) parts. If a vehicle with a VIN prior to the production change requires a trim panel replacement, all three pieces must be replaced **as a set**.

The service procedures for replacing the rear gate trim panels remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to: important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair. Customer satisfaction and retention starts with performing quality repairs.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.