TECHNICAL BULLETIN 05 JUN 2018



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

501-18: Folding Top

SUBJECT/CONCERN:

Scratches Visible On Upper Rear Quarter Panel

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
F-TYPE (X152)	2016	K24802-K31384	Castle Bromwich

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

This issue affects F-TYPE Project 7 models only.

SITUATION:

Scratches may be visible in the paintwork on the upper rear quarter panels or the rear quarter window frame seals may be damaged.

CAUSE:

This may be caused by the rear quarter window frames contacting the rear quarter panels.

ACTION:

Should a customer express this concern, follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
T2R29420	Rear quarter window frame seal kit	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

\wedge

NOTES:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time. ■ The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Rear quarter window frame seal - Modification	76.86.65	0.3	30	T2R29420



∧ NOTE:

Normal Warranty procedures apply.

WORKSHOP PROCEDURE:

Replace the rear quarter window seal (see TOPIx Workshop Manual section 501-18: Folding Top -Removal and Installation - Rear Quarter Window Seal - Project 7).