

XF
F-TYPE
15-16MY
Equipped with
AJ126
3.0L Engine

A Customer may experience a coolant leak or engine overheat condition.

Inspection identifies loss of coolant from the seam of the thermostat housing or the housing split. Repair the coolant leak by replacing the thermostat and hold the parts for analysis. Submit an EPQR with contact information of someone at the retailer who can support PRR.



Under
Investigation