

SSM 47383	Some 2018 F-150 vehicles equipped with a 3.0L diesel engine may have DTC U0415 set in the powertrain control module (PCM) after a key on engine off (KOEO) or key on engine running (KOER) self-test. Do not attempt any repairs for this DTC at this time. Monitor OASIS for updates.
--------------	--