



GROUP  
**Electrical**

MODEL  
**2017-2018MY  
Sportage (QL)**

NUMBER  
**PS569**

DATE  
**June 2018**



## TECHNICAL OPERATIONS

**SUBJECT:**

### INAUDIBLE TURN SIGNALS AND NO SEAT BELT AND KEY WARNING CHIME

This Pitstop provides information regarding an inoperative cluster speaker on 2017-2018MY Sportage (QL). Customer concern may include inaudible turn signals and no seat belt and key/key fob warning chimes. If all three (3) of these systems do not sound, it may be necessary to inspect the cluster speaker assembly and/or circuit. If the cluster speaker circuit is found to be within specifications, it may be necessary to replace the speaker assembly.

