



Bulletin No.: PIP5568A

Published date: N/A

Preliminary Information

PIP5568A Service Engine Soon Light Comes on With All 4 Camshaft Position System Performance DTCs P0011, P0014, P0021 and P0024 Setting.

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018	All	All	3.6 LFY	All
Buick	LaCrosse	2017 - 2018	All	All	3.6 LGX	All
Buick	Regal	2018	All	All	3.6 LGX	All
Cadillac	ATS	2016 - 2018	All	All	3.6 LGX	All
Cadillac	CT6	2016 - 2018	All	All	3.0 LGW, 3.6 LGX	All
Cadillac	CTS	2016 - 2018	All	All	3.6 LGX	All
Cadillac	XT5	2017 - 2018	All	All	3.6 LGX	All
Chevrolet	Traverse	2018	All	All	3.6 LFY	All

Involved Region or Country	North America
Condition	Some customers may come in with a MIL/SES illuminated and no drivability concerns.
Cause	Tech will find P0011, P0014, P021, and P0024 ALL set in the ECM.

Correction:

Clear the codes and return the vehicle to the customer.
 At this time the cause for this concern is under investigation.
 Please do not replace any parts for the concern at this time.

NOTE: We will update the PI or create a bulletin to replace this PI when more information becomes available.

Version History

Version	2
Modified	Created on 05/07/2018. Updated 6/26/2018 to update Correction Section.



GENERAL MOTORS