

**Fault P029900 Stored In The DME Due To Loose Vacuum Line**


Binder – 2 – Engine-Electric  
This bulletin replaces ATI Grp 2 1702  
published on April 6, 2017.

Vehicle Type: **Panamera 4S/Turbo (971)**

Model Year: **All**

Issue: Fault **P029900-Turbo/Super Charger Underboost** stored in the DME.

Information: A vacuum line at the vacuum reservoir in the left front wheel well was not connected properly during production and may become disconnected (see the picture below). The repair is to simply reconnect the line and make sure it is not under tension.



Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, Tiptronic®, VarioCam®, PCM®, PDK®, 911®, RS®, 4S®, 718®, 918 Spyder®, FOUR UNCOMPROMISED®, and the model numbers and distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. However, specifications, standard equipment and options are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. Please ask your authorized Porsche dealer for advice concerning the current availability of options and verify the optional equipment that you ordered. Porsche recommends seat belt usage and observance of traffic laws at all times.