



SI B71 02 18
Tools and Accessories (Engine-Chassis)

May 2018
Technical Service

UPDATE ! VOLUNTARY EMISSIONS RECALL CAMPAIGN 18E-A02: REPLACE UNDER HOOD EMISSIONS LABEL

New information provided by this revision is preceded by this symbol **UPDATE !**.

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

This Service Information bulletin replaces SI B71 02 18 **dated March 2018**

What's New:

- Delivery Stop changed to a Voluntary Emissions Recall

MODEL

F30 (3 Series)			
----------------	--	--	--

Produced between November 14, 2017 and February 11, 2018.

SITUATION

The affected vehicles were equipped with an incorrect **emissions label** which must be replaced.

UPDATE ! AFFECTED VEHICLES

This Emissions Recall Campaign affects approximately 1,032 vehicles produced between November 14, 2017 and February 11, 2018.

First check if a Recall Completion Label, SD 92-435 for this campaign is already attached to the underside of the hood on the right (passenger) rear close to the windshield.

If the label is present, the Campaign has already been performed and no further action is necessary.

Affected vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

Owners will be notified in May 2018 via First Class mail, advising them of this recall.

CAUSE

An incorrect model year 2017 emissions label was installed on the model year 2018 vehicle.

CORRECTION

Replace the current label with the correct model year 2018 emissions label.

PROCEDURE

For all affected vehicles:


	1. Access engine compartment area
	2. Verify the incorrect MY 2017 emissions label is installed 3. Remove label and clean glue residue from surface area with an approved cleaner 4. Adhere correct MY 2018 emissions label

PARTS INFORMATION

Replace the current label with the correct model year 2018 emissions label.

Part Number	Description	Quantity
Refer to ETK	Model Year 2018 Emission Label	1

LABEL INSTRUCTIONS

	After the vehicle has been checked and corrected, obtain a label (SD 92-435) and with the indelible marker provided, legibly print the Recall name, Recall number, and dealer code (5 digits) on the “Emissions Recall Campaign Completed Label” (see illustration). Note: Additional labels can be ordered online at BMW TIS.
---	---

WARRANTY INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the following information:

Defect Code:	0071450200	
--------------	------------	--

Completion before vehicle delivery to the customer or the vehicle is already in the workshop

--	--	--

Labor Operation:	Labor Allowance:	Description:
00 66 540	3 FRU	Replace the emissions label (Plus work)

Or:

Completion after vehicle delivery to the customer

Labor Operation:	Labor Allowance:	Description:
00 66 027	5 FRU	Replace the emissions label (Main work)

Posted: Monday, May 7, 2018

ATTACHMENTS

View PDF attachment [B710218 Delivery Stop Legal](#).

[Copyright ©2018 BMW of North America, Inc.]

Please be reminded that it is a violation of Federal law for you to sell, lease or deliver any vehicle covered by this notification until the delivery stop repair has been performed. This means that centers may not legally deliver new motor vehicles to a consumer until it is fixed or use/sell replacement equipment/parts subject to a delivery stop. Note also that substantial civil penalties apply to violations of this law.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a delivery stop until the repair is completed.