




Technical Information Bulletin

26-031



Section

Transmission—Main, Manual - 26

Subject

Manual or UltraShift Transmission Bellhousing Bolt Torque Resolution and Warranty Claim Window

Release Date

6/28/2018

Condition

Some chassis experienced a loss of clamp load of the bellhousing bolts related to the surface finish on the bellhousing.

Chassis Affected

Chassis with manual or UltraShift transmissions built from 01/01/2018 through 04/27/2018.

Action

INFORMATION ONLY

Kenworth Field Service had previously initiated proactive instructions to re-torque bellhousing bolts.

Warranty

In the past few months, the field has seen instances of loose transmission bellhousing bolts. The issue was related to the surface finish which impacted torque and clamp load. Corrective action was quickly initiated at all factories, and the clean point for units delivered from Kenworth factories is 04/27/2018. Warranty claims in process and repairs completed before 07/04/2018 will be honored.

Authored by: OF

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2018 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).