




Technical Information Bulletin

E213A



Section

Engine

Subject

Dash Lamp Optimization Campaign – DPF Pressure Sensor

Release Date

6/12/2018

Revision

6/28/2018: Chassis List has been updated.

Condition

The vehicle has been flagged as having met certain lamp time performance criteria.

Chassis Affected

Specific chassis equipped with PACCAR MX-13 EPA2013 and 2017 engines.

Action

Campaign

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. If you are not using Service Management to start repair orders, review DWWC or SIR for "Complete" next to the "E213A" campaign code prior to performing this repair.
3. Also, complete ALL other open campaigns.
4. Follow the procedures below to make repairs as listed in the chassis list attached to this bulletin.

Warranty

WARRANTY

Through Standard Warranty (excludes Extended Warranty) or for repairs completed by 12/31/2019, whichever is greater, Kenworth will pay for parts at dealer net plus applicable mark-up and labor:

- 1.3 hours labor to replace the DPF Pressure Sensor and run a stationary regen for EPA2013 engines. Use Quick Claim code E213AA.
- 0.8 hours labor to replace the DPF Pressure Sensor and run a stationary regen for EPA2017 engines. Use Quick Claim code E213AB.
- File a separate claim if diagnostics are required after replacing the part.
- For chassis that have an open campaign(s), file a claim for the campaign(s).

Kenworth dealers may perform E213A repairs on Peterbilt chassis, but Quick Claims do not apply. For Peterbilt chassis repairs, use the long claim input form in DWWC selecting "Draft/Offline Claims", the "General" tab, and in the "Type of Claim" drop down box, select "PACCAR Engine Claim", then manually enter claim codes (Campaign #, Failure type, and SRT).

CLAIM CODING			
Failure Location:	043-006-007	Work Accomplished:	35
Failure Type:	185	Responsibility Code:	01
SRT Code:	043-845 (0.7 hrs. EPA2013, 0.2 hrs. EPA2017) R&R DPF Sensor 043-635 0.6 hrs. Run Stationary Regen	Claim Type:	F

Parts

Parts are available from PACCAR Parts.

If a part number supersedes, **ALWAYS** use the latest available part number for this bulletin.

Quantity	Part Number	Description
1	1818119PE	DPF Pressure Sensor

Procedure

1. Replace the DPF Pressure Sensor.
 2. Run a Stationary Regen and monitor for proper operation.
 3. If the DTCs listed on the chassis list are still active, perform appropriate troubleshooting.
-

Attachments



Authored by: OF

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2018 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).