



Preliminary Information

PIT5623A Intermittent Antilock Brake System (ABS) Light and Service StabiliTrak Message with Dual Rear Wheels

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Express	2018	All	All	All	All
GMC	Savana	2018	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	R05 (Dual Rear Wheels)
Condition	Intermittent Antilock Brake System (ABS) Light And Service StabiliTrak message with dual rear wheels setting C0050 Sym0F
Cause	Engineering is currently investigating concern on vehicles not repaired after following published diagnostics.

Correction:

If after following published Service Information diagnostics for C0050 SYM0F and no correction is found, clear DTC's and release vehicle to customer. Question customer see if this concern only occurs after driving on rumble strips on the right side of the road. Do not attempt repairs for this concern. Engineering is aware of the concern and working on a field fix. This PI will be updated when the repair is available.

NOTE: Other Symptom codes should be diagnosed using SI.

Version History

Version	2
Modified	6/26/2018 - Created 7-16-2018 - Updated on 7/16/2018 to update recommendations.



GENERAL MOTORS