

Bulletin No.: PIP5568B Published date: 07/26/2018

Preliminary Information

PIP5568B Service Engine Soon Light Comes on With All 4 Camshaft Position System Performance DTCs P0011, P0014, P0021 and P0024 Setting.

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions
			from	to	Engine:	Transmissions:
Buick	Enclave	2018 - 2019	All	All	3.6 LFY	All
Buick	LaCrosse	2017 - 2019	All	All	3.6 LGX	All
Buick	Regal	2018 - 2019	All	All	3.6 LGX	All
Cadillac	ATS	2016 - 2019	All	All	3.6 LGX	All
Cadillac	СТ6	2016 - 2019	All	All	3.0 LGW, 3.6 LGX	All
Cadillac	стѕ	2016 - 2019	All	All	3.6 LGX	All
Cadillac	XT5	2017 - 2019	All	All	3.6 LGX	All
Chevrolet	Traverse	2018 - 2019	All	All	3.6 LFY	All
Involved Region or Country North America						
Condition		Some customers may come in with a MIL/SES illuminated and no drivability concerns.				
Cause		Tech will find P0011, P0014, P021, and P0024 ALL set in the ECM.				

Correction:

Clear the codes and return the vehicle to the customer. At this time the cause for this concern is under investigation. Please do not replace any parts for the concern at this time.

NOTE: We will update the PI or create a bulletin to replace this PI when more information becomes available.

Version History

Version	3
	Created on 05/07/2018.
Modified	Updated 6/26/2018 to update Correction Section.
	Updated 7/25/2018 to include 2019 MY



GENERAL MOTORS

 $\ensuremath{\mathbb{C}}$ 2018 General Motors. All Rights Reserved.