

SERVICE BULLETIN

Classification:

Reference:

Date:

BT17-003a

NTB17-023a

July 11, 2018

2017-2018 ARMADA; OUTSIDE MIRROR(S) LOOSE AT BASE

This bulletin has been amended. A model year has been added to APPLIED VEHICLES. Discard all previous versions of this bulletin.

APPLIED VEHICLES: 2017-2018 Armada (Y62)

SERVICE INFORMATION

If the power foldable outside mirrors are manually folded/unfolded or bumped, the mirror body can become loose at the pivot point.

If this occurs, the mirrors should be adjusted again electrically before driving.

To readjust the mirrors, press the "CLOSE" switch (see Figure 1) until the mirrors are fully folded in, and then press the "OPEN" switch until the mirrors are fully open.

This mirror readjustment procedure is included in section **3** - **Pre-driving checks and adjustments** of the vehicle Owner's Manual.

NOTE:

- <u>DO NOT</u> replace the power foldable outside mirrors for this condition, should it occur.
- This condition is not covered under the Nissan New Vehicle Limited Warranty.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.