ATTENTION:					
GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL	IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.				
SERVICE MANAGER	© 2018 Subaru of	f Ameri	ca, Inc.	All right	ts reserved.



QUALITY DRIVEN® SERVICE

NUMBER: 12-247-18

DATE: 07/31/18

SERVICE INFORMATION BULLETIN

APPLICABILITY:	2017-2018MY Impreza 5-Door 2017-2018MY Crosstrek
SUBJECT:	Cargo Cover Installation Reminder

INTRODUCTION:

This Service Information bulletin serves as a reminder to always make sure the rear cargo cover (a.k.a. Tonneau Cover) is re-installed properly after removal. Although the cover fits and operates if not installed properly, wrinkling and / or damage to the cover material can occur as shown in the images below.


On the right side (spring-loaded) end cap portion of the housing, there is a double-ended arrow image molded into the plastic to represent how to move the cover assembly laterally to remove / install it. It is critical for the arrows to face upward for proper operation of the cover assembly and to prevent wrinkling or damaging the cover material.

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

• Correct Installation:

The outlet for the cover on the housing faces the back of the car.



Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

ISO 14001 Compliant ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotiveproducts in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.


Subaru of America, Inc. is

• Incorrect Installation:

If the housing is rotated 90 degrees and installed that way, the outlet for the cover will point downward toward the floor. If this occurs, the cover material may get caught in the push guide area and cause wrinkles or other damage.



In addition, the applicable Owners Manuals will be updated soon.



IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.