

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2017080006, March 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Models 205, 217, 222, and 253 Model Years 2014 - 2018**
Update fuel system control unit (FSCU) software

Daimler AG ('DAG'), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY14-18 205, 217, 222, and 253 platform vehicles (C-Class, S-Class, S-Class Coupe, GLC-Class) the fuel system control unit (FSCM) software does not correspond to current production specification. As a result, certain faults stored in the control unit might not be recognized and therefore would not activate the engine control lamp in the instrument cluster. An authorized Mercedes-Benz dealer will update the fuel system control unit software on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.







Approximately 110,507 vehicles are affected.

Order No. P-SC-2017080006

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Procedure

i Note:

- Use DAS/Xentry 07/17 with all associated patches or higher.
 - Follow the steps exactly as described in DAS/Xentry.
 - Connect battery charger (battery voltage  >12.5V).
 - Ensure all electrical consumers are switched-off.
 - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the “pre-call” check list before contacting UHD
 - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. **Update fuel system control unit (FSCU) software:** Control units  Drive type  FSCU- Fuel view system control unit  Adaptations  Control unit update  Update of control unit software.
 2. Follow on-screen instructions.

i Note:

The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)
 Star Diagnosis System (SDS), Connect/disconnect (02-4762)
 Update fuel system control unit (FSCU) software (02-9334)

Damage Code	Operation Number	Labor Time (hrs.)
54 991 48 8	02-5058	0.1
	02-4762	0.1
	02-9334	0.1

i Note:

Operation Number labor times are subject to change.