

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2018040004, May 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 156 Model Year 2018**
Attach exhaust treatment information label

Daimler AG (“DAG”), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY18 156 (GLA-Class) vehicles, the information label containing the exhaust gas cleaning information was not installed. An authorized Mercedes-Benz dealer will attach the exhaust gas cleaning information label on the affected vehicles.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 1,483 vehicles are affected.

Order No. P-SC-2018040004

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

1. Open hood.
2. Attach exhaust treatment information label **(A)** (figure 1).

i Clean area intended for the information label.




Figure 1

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	Exhaust gas cleaning information label	A 270 221 17 00	100%

Warranty Information

Operation: attach exhaust treatment information label (02-2274)

Damage Code	Operation Number	Labor Time (hrs.)
58 916 50 7	02-2274	0.3

i **Note**

Operation Number labor times are subject to change.