



Countries: UNITED STATES, MEXICO **Document ID:** IK0800536
Availability: ISIS, NotSIR **Revision:** 4
Major System: ELECTRICAL SYSTEM **Created:** 2/9/2017
Current Language: English **Last Modified:** 7/27/2018
Other Languages: NONE **Author:** Andrew Boyd
Viewed: 252

[Less Info](#)
☒ Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 9	Not Helpful 0
---------------	------------------------	---	----------------------	-----------	----------------------	------------------	----------------------

Title: LT Starter programming update

Applies To: LT with Auto Start Stop

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

09/23/2015 - Initial Article Release
 07/16/2018 - Republished and updated for new LT E-FIX 1089

DESCRIPTION

This document will guide the user through information out for Updating the body controller for all LT with Auto Start Stop.

This applies ONLY to LT vehicles with Auto Start Stop.

When the body controller is updating to Software version 289, there will be new parameters under the below feature codes.

0597041 – For Cummins Engines


0597250 – For International Engines.

SYMPTOM(s)

Starter failures early in life.

REPAIR STEP(s)

Connect to the vehicle via DLB, complete a get from history on the vin you're working on. Once connected, highlight the chassis number you're working on and select update software. Once that step is completed and programming is finished you will see Data Version 289 in selected and detected. No further steps need to be taken to complete this update.



WARRANTY INFORMATION

Standard Repair Time(s):

Refer to the [SRT Manual](#) for Repair Times

OTHER RESOURCES

[Master Service Information Site](#)

Hide Details

Feedback Information

Viewed: 251
Helpful: 9
Not Helpful: 0

No Feedback Found

Copyright © 2018 Navistar, Inc.