



GROUP
Climate

MODEL
2017-2019MY
Sportage (QL)
2015-2018MY
K900 (KH)

NUMBER
PS578


DATE
September 2018




TECHNICAL OPERATIONS

SUBJECT: IDENTIFYING A SEIZED COMPRESSOR

This Pitstop provides information regarding the diagnosis of an A/C related concern on 2017-2019MY Sportage (QL) and 2015-2018MY K900 (KH) vehicles that may have a seized compressor. To confirm the diagnosis of a seized A/C compressor, visually inspect for a paint mark (A) against the limiter in the center of the compressor. If the mark is no longer aligned (B), an internal disconnection of the limiter has occurred and the compressor assembly needs to be replaced.



Marks **Aligned** (Not Seized)



Marks **Not Aligned** (Seized)