

Audio 20: Clock is slow in vehicles without navigation.

Topic number	LI54.30-P-066875
Version	5
Function group	54.30 Instrument cluster, display instruments, hazard warning device
Date	06-19-2018
Validity	Model 205, 253 with code 520 or 522, without code 355 and 154.
Reason for change	Remedy adapted.
Reason for block	

Complaint:

In vehicles without pre-installation for navigation, the clock may be slow (by approx. 5-10 minutes per month).

Cause:

Software of Audio20 control unit (A26/17).

Remedy:

Software update of Audio20 control unit (A26/17) to software release 18/03.00.

The required software release is available with XENTRY version 05/2018 or newer.

Symptoms
Communication/information / Information display / Displays / Clock / Too slow

Control unit/fault code		
Control unit	Fault code	Fault text
A2 / A40/3 / A26/17 - Audio or COMAND, A40/3 / A26/17 - Audio or COMAND (Audio) (HU5_ENTRY)	-	-