

**Bulletin No.:** PIC6124D **Published date:** 08/30/2018

# **Preliminary Information**

### PIC6124D T18 Battery Charge Module (OBCM) Part Restriction

#### Models

Brand: Model:		Model Years:	VIN:		Engino	Transmissions:	
branu.	Model.	Model fears.	from	to	Engine:	Transmissions.	
Chevrolet	Volt	2016 - 2019	All	All	All	All	

#### **Supersession Statement**

This PI was superseded to add part # 24277908 Please discard PIC6124D.

#### Condition / Concern

As part of our ongoing quality improvement process, the T18 Battery Charger (OBCM) for the Chevrolet Volt is on restriction through the GM TAC (Technical Assistance Center) as of August 1st, 2015.

#### Recommendations / Instructions

1) Please have a certified Volt technician follow the procedures below prior to contacting TAC.

IMPORTANT: Note Do NOT erase DTC's in any of the modules (especially on intermittent concerns) and do NOT attempt to reprogram software!

- 2) Please complete the customer questions below with as much information as possible and as accurately as possible so that it can be emailed to TAC.
- 3) Check and record all diagnostic codes in all modules on the vehicle.
- 4) Be sure to record what module the DTC came from and any symptom codes associated with the DTCs (see latest version of bulletin 10-07-30-002 for snapshot information).
- 5) Please save the DTC captured data for later use.
- 6) Description of the concern (both customer and technician).
- 7) Charging at 110V vs 240V?
- 8) OEM cord set, wall station, or aftermarket equipment? If aftermarket supplier, include make and model number.
- 9) Location (residential or public charge station, generator, other)?
- 10) HPCM 2 software level
- 11) Once the above information has been obtained, please review all PI and TSB information as well as all available S.I. diagnostics.
- 12) If diagnostics lead to OBCM replacement, contact TAC @ 877-446-8227 (U.S.) or in Canada 1-800-263-7740 (English) or 1-800-263-7960 (French) to review case details. Please have as much stored DTC and snapshot information as possible prior to contacting TAC.
- 13) If it is determined that component replacement is needed after reviewing the diagnosis, TAC will arrange for ordering of the new component and request that it be shipped overnight.

NOTE: When this occurs, record the last 9 digits of the TAC case # to be used by the parts department (in conjunction with the part #) as the CONTROL NUMBER to track shipment of the part. It is not necessary to call TAC for part tracking information.

#### Parts Information

YEAR / MAKE / MODEL	COMPONENT CODE	PART NAME	PART NUMBER	QUANTITY
I .	1			

2016 Chevrolet Volt	T18	Drive Motor Battery Charger	24275451 FSU 24286781	1
		Replacement		
<del>2017 - 2019 Chevrolet</del>		Drive Motor Battery Charger		
Zori Zori enevioled	T18		24281923 FSU 24286781	1
Volt		Replacement		
2019 Optional 7.2	T10	Drive Motor Battery Charger	24277000	1
(RPO K23)	T18	Replacement	24277908	'

## Warranty Information

Labor Operation	Description	Labor Time	
5040210 Drive Motor Battery Charger Replacement		Use Published Labor Operation Time	

















### GENERAL MOTORS

© 2018 General Motors. All Rights Reserved.