

Published date: 08/30/2018

Preliminary Information

PIT5628 Fog Lamp Indicator Inoperative on IPC after Installing the Accessory Fog Lamp Kit

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to	Engine.	
Chevrolet	Colorado	2018 - 2019	All	All	All	All
GMC	Canyon	2018 - 2019	All	All	All	All

Involved Region or Country:	North America	
Additional RPO/s:	None	
Condition:	Fog lamp indicator is inoperative in the IPC after installing the accessory fog lamp kit.	
Cause:	The IPC also needs to be programmed for the new option.	

Correction:

If the fog lamp indicator does not come on with fog lamps or for bulb check the IPC needs to be programmed with a VCI number . Contact Techline at 800-828-6860 for calibration information.

Version History

Version	1.0
Modified	Created 08/20/2018



© 2018 General Motors. All Rights Reserved.