

Range Rover Velar (Dynamic only)	False activation of the front PDC	We have received a number of reports through GCM of false activation of the front PDC when there is nothing in front of the vehicle. Engineering have determined root cause to be the fluctuation of the bumper in high ambient temperatures. This issue only affects Dynamic models as the front bumper is different from the standard bumper. Software is currently being developed to resolve this concern and a bulletin will be published when available. If you should have a customer with this concern, please continue to raise EPQRs.	SSM 73955
--	--------------------------------------	---	-----------