

RR Velar	A Customer may report that the tail lamp appears to be delaminating or cracking.	<p>Engineering are currently investigating cases where the tail lamps appear to be delaminating or cracking. Please report any cases you find of this concern via EPQR with pictures of the tail lamp concern and the date codes on the back of the lamp assembly to support the investigation. For any unsold vehicles with no customer delivery imminent, we ask that you submit an EPQR and hold-off removing the lamp as engineering would like to inspect the lamp before removal from the vehicle. Order the replacement lamp, but do not install it until the vehicle has been inspected by engineering.</p>	Under Investigation
			