



23Y9 Campaign Tip

Differential/Exhaust Pressure Sensors

This notice is for:	✓ Dealer Principal ✓ Sales Manager	✓ Service Manager ✓ Parts Manager	✓ Warranty Administrator ✓ Technicians
Date	May 23, 2018		
Issue	Differential/Exhaust Pressure Sensors cracking due to improper removal or storage.		
Resolution	<p>The bolts for the Differential and Exhaust Pressure Sensors and mounting bracket fastener/s must be removed before removing or disturbing the pressure sensor pipes secured on the timing cover.</p> <p>The labor operations contained in the 23Y9 Campaign Circular MUST be followed IN THE ORDER WRITTEN during removal/reinstallation of the Exhaust Pressure Sensors. The sensors <u>ARE FRAGILE</u> and can be damaged if:</p> <ul style="list-style-type: none">• Order of operations in the 23Y9 are not followed.• Excessive or unnecessary force is used.• Sensors are not stored or handled with care.		