
ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the hoxes provided, right.



© 2018 Subaru of America, Inc. All rights reserved.



SERVICE INFORMATION BULLETIN

APPLICABILITY: NUMBER: 12-248-18 2017-2018MY Legacy

SUBJECT: Trunk Hinge Flange Bolt Change **DATE:** 08-09-18

INTRODUCTION:


This Service Information bulletin announces a change made to the trunk hinge mounting bolts. The threaded end of the new flange bolts has been changed to a round type instead of square to prevent getting caught on items as they are loaded into and out of the trunk.

PRODUCTION CHANGE INFORMATION:

This bulletin will be updated with the starting VIN for the production change when it becomes available.

PART INFORMATION:

The part number for the new flange bolts is: 901000458.



Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Bulletin Number: 12-248-18; Date: 08/09/18

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs. The service procedures and torque specifications for these new trunk hinge flange bolts remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 12-248-18; Date: 08/09/18 Page 2 of 2