



CAMPAIGN BULLETIN

Fuel Injector Replacement Retailer Inventory

Reference: P8315
Date: August 3, 2018

Attention: Retailer Principal, Sales, Parts and Service Managers

Affected Models/Years:	Affected Population:	Retailer Inventory:	SERVICE COMM Activation date:	Stop Sale In Effect
MY2019 QX50 (J55)	NA	53*	July 20, 2018	NO

* Please refer to the open campaign report provided with this campaign update for retailer specific affected units.

***** Parts Update *****

100% of retailer inventory parts need was automatically shipped to affected retailers the week of July 23, 2018.

The purpose of this update is to inform retailers that 14035-5NAOA Intake Manifold Gaskets are on temporary parts restriction. Intake manifold gaskets may be incorrectly packaged and a PDC stock check is currently in progress to confirm. **If necessary**, retailers may place a replacement order via DBS as an SVC order type only.

Orders will be filled **as parts become available** on a first in, first out basis. Retailers should ensure that the correct part numbers and quantities are ordered for each VIN. Retailers can refer to IPSB16-384 for specific ordering instructions.

As mentioned above, retailers should already have enough parts to repair affected inventory need with the exception of any incorrectly packaged 14035-5NAOA Intake Manifold Gaskets.

Any parts necessary for this repair that are not restricted will need to be placed separately via normal ordering process.

***** Part Number *****

Part Number	Description
14035-5NAOA	GASKET-INTAKE MANIFOLD