#### ATTENTION:

GENERAL MANAGER

PARTS MANAGER

CLAIMS PERSONNEL

SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.



QUALITY DRIVEN® SERVICE

SUBARU

**NUMBER:** 15-233-18

**DATE:** 08/29/18

© 2018 Subaru of America, Inc. All rights reserved.

# SERVICE INFORMATION BULLETIN

**APPLICABILITY:** 2017-2019MY Impreza

2017-2019MY Crosstrek

2019MY Ascent 2019MY Forester

All above models with Harman 8" Touch Screen Display Audio or Navigation Equipped Audio Units

SUBJECT: Display / Touch Screen "Soft Keys" -Delayed

Response

### **INTRODUCTION:**

This Service Information bulletin provides a procedure to use for addressing a customer concern of a delayed or slow response when using the soft keys on the touch screen of the audio / navigation head unit.

### **MATERIALS REQUIRED:**

- A CLEAN (preferably new), soft micro-fiber cloth or towel
- Aerosol can of "Sprayway" -brand, Ammonia-free glass cleaner, available at most major retailers and home improvement stores

#### **SERVICE PROCEDURE / INFORMATION:**

**REMINDER:** Customer satisfaction and retention starts with performing quality repairs.

#### **IMPORTANT CAUTIONS:**

- DO NOT spray the glass cleaner directly onto the display screen.
- Do NOT use a cotton towel or shop cloth which can easily scratch the display screen.
- Always confirm the protective film has been removed from the display screen.
- Apply the glass cleaner to the CLEAN micro-fiber cloth.
- LIGHTLY wipe the display screen to remove any dust or dirt until clean.

#### Continued...

# CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

# Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Spraywo
Wirt's lest

Glass

Cleaner

Liss streakless

Bis streakless

Wirth and the streakless

Bulletin Number: 15-233-18; Date: 08/29/18

Page 1 of 2

## **IMPORTANT REMINDERS:**

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 15-233-18; Date: 08/29/18 Page 2 of 2