

Field campaign

| | |
|------------------------|--|
| Topic | Trim Strip For Rear Panel Brake Light - Blackware - Paint Adhesion (SC18/05) |
| Market area | Australia E04 Bentley rest Asia and Australia (6E04),Germany E02 Bentley rest Europe (6E02),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05) |
| Brand | Bentley |
| Transaction No. | 2049646/2 |
| Campaign number | EB02 |
| Note | |
| Type | Workshop Campaign |
| US code | |

Vehicle data

Bentley Continental GTC / Supersports GTC

Sales types

| Type | MY | Brand | Designation | Engine code | Gearbox code | Final drive code |
|------|------|-------|-------------|-------------|--------------|------------------|
| 394* | 2017 | E | | * | * | * |
| 394* | 2018 | E | | * | * | * |

Chassis numbers

| Manufacturer | Filler | Type | Filler | MY | Factory | From | To | Prod from | Prod to |
|--------------|--------|------|--------|----|---------|--------|--------|-----------|---------|
| SCB | GB3 | ZA | 7 | J | C | 066697 | 066697 | | |
| SCB | GB3 | ZA | 0 | J | C | 066699 | 066699 | | |
| SCB | GB3 | ZA | 1 | J | C | 066422 | 066422 | | |
| SCB | GB3 | ZA | 8 | J | C | 066823 | 066823 | | |
| SCB | GB3 | ZA | 0 | J | C | 066458 | 066458 | | |
| SCB | GB3 | ZA | 2 | J | C | 066624 | 066624 | | |
| SCB | GB3 | ZA | 8 | J | C | 066496 | 066496 | | |
| SCB | GB3 | ZA | 6 | J | C | 066416 | 066416 | | |
| SCB | GB3 | ZA | 1 | J | C | 066579 | 066579 | | |
| SCB | GB3 | ZA | 6 | J | C | 066545 | 066545 | | |
| SCB | GB3 | ZA | 6 | J | C | 066576 | 066576 | | |
| SCB | GB3 | ZA | 8 | J | C | 066627 | 066627 | | |
| SCB | GB3 | ZA | X | J | C | 066418 | 066418 | | |
| SCB | GB3 | ZA | 7 | J | C | 066702 | 066702 | | |
| SCB | GB3 | ZA | 1 | J | C | 066730 | 066730 | | |
| SCB | GF2 | 3W | 4 | J | C | 066420 | 066420 | | |
| SCB | GF2 | 3W | 1 | J | C | 066424 | 066424 | | |
| SCB | GF2 | 3W | 9 | J | C | 066414 | 066414 | | |
| SCB | GE2 | 3W | 6 | J | C | 066602 | 066602 | | |
| SCB | GE2 | 3W | 5 | J | C | 066364 | 066364 | | |
| SCB | GF2 | 3W | 5 | J | C | 066426 | 066426 | | |
| SCB | GE2 | 3W | X | J | C | 066408 | 066408 | | |
| SCB | GR2 | 3W | X | J | C | 066607 | 066607 | | |
| SCB | GE2 | 3W | 4 | J | C | 066372 | 066372 | | |
| SCB | GF2 | 3W | 3 | H | C | 066399 | 066399 | | |
| SCB | GF2 | 3W | 9 | H | C | 066410 | 066410 | | |
| SCB | GF2 | 3W | 7 | H | C | 066633 | 066633 | | |
| SCB | GF2 | 3W | 8 | J | C | 066470 | 066470 | | |
| SCB | GF2 | 3W | X | J | C | 066664 | 066664 | | |
| SCB | GF2 | 3W | 1 | J | C | 066455 | 066455 | | |
| SCB | GF2 | 3W | 5 | J | C | 066474 | 066474 | | |
| SCB | GF2 | 3W | 6 | H | C | 066428 | 066428 | | |
| SCB | GF2 | 3W | 2 | J | C | 066688 | 066688 | | |
| SCB | GF2 | 3W | 7 | J | C | 066461 | 066461 | | |

| | | | | | | | | | |
|-----|-----|----|---|---|---|--------|--------|--|--|
| SCB | GF2 | 3W | 1 | J | C | 066567 | 066567 | | |
| SCB | GF2 | 3W | X | J | C | 066499 | 066499 | | |
| SCB | GE2 | 3W | 5 | J | C | 066767 | 066767 | | |
| SCB | GE2 | 3W | 8 | J | C | 066472 | 066472 | | |
| SCB | GB3 | ZA | 7 | J | C | 066487 | 066487 | | |
| SCB | GB3 | ZA | 2 | J | C | 066753 | 066753 | | |
| SCB | GB3 | ZA | 6 | J | C | 066609 | 066609 | | |
| SCB | GB3 | ZA | 1 | J | C | 066713 | 066713 | | |
| SCB | GB3 | ZA | 6 | J | C | 066707 | 066707 | | |
| SCB | GB3 | ZA | 1 | J | C | 066467 | 066467 | | |
| SCB | GB3 | ZA | 5 | J | C | 066570 | 066570 | | |
| SCB | GB3 | ZA | 0 | J | C | 066539 | 066539 | | |
| SCB | GB3 | ZA | 1 | J | C | 066551 | 066551 | | |
| SCB | GB3 | ZA | 1 | J | C | 066484 | 066484 | | |
| SCB | GB3 | ZA | X | J | C | 066502 | 066502 | | |
| SCB | GB3 | ZA | 6 | J | C | 066478 | 066478 | | |
| SCB | GB3 | ZA | 2 | J | C | 066493 | 066493 | | |
| SCB | GB3 | ZA | 6 | J | C | 066481 | 066481 | | |
| SCB | GB3 | ZA | X | J | C | 066581 | 066581 | | |
| SCB | GB3 | ZA | 7 | J | C | 066618 | 066618 | | |
| SCB | GB3 | ZA | 1 | J | C | 066548 | 066548 | | |

Documents

| |
|----------------------|
| Document name |
| master.xml |

-

Notes

□ [Repair instructions](#)

Technical background

A small number of Rear Panel - Brake Light Trim Strip Assemblies have blackware finishers painted using an incorrect procedure.

Remedy

Replace the Rear Panel - Brake Light Trim Strip Assembly.



Customer notification

Customers do not need to be informed directly of this campaign. Please ensure that all affected vehicles are checked and repaired during a service visit. You should also inform your new and used car sales departments so that the vehicles affected can be checked and, if necessary, repaired immediately and not just before sale.

Warranty

| | |
|-----------------------|---|
| Warranty Type | 710 or 790 |
| Labour Operation Code | 61 23 19 02 (for Continental GT convertible) 61 23 19 00 (for Supersports convertible) |
| Damage Service Number | EB02 |
| Damage Code | 00 66 |
| Time | 110 TU |
| Criteria ID | 01 |

Parts

The required replacement parts should be ordered from Bentley Motors Limited Crewe or through your regional Bentley parts distribution centre.

Parts supply

3W7 853 327F – Assembly Trim Strip for Rear Panel Brake Light – 1 off.

Parts despatch control

.

Technical background

A small number of Rear Panel - Brake Light Trim Strip Assemblies have blackware finishers painted using an incorrect procedure.

Check

If the vehicle is not already listed as repaired in the "Repair history" (in Elsa pro), check for the presence of a white campaign identification mark on the convertible roof mechanism - see Figure 1 - should neither be evident carry out the required work in accordance with these instructions.



Figure 1

Parts

The required replacement parts should be ordered from Bentley Motors Limited Crewe or through your regional Bentley parts distribution centre.

Work

Refer to **Repair Group 94 Lights, lamps, switches outside – Lamps – High mounted stop lamp (HMSL) – To remove and fit**, follow the procedure until the instruction **"With the aid of an assistant, carefully remove the "brightware/blackware" assembly from the vehicle and place fixing side up on a protective surface"**.

Fit new assembly - 3W7 853 327F - refer to **Repair Group 94 Lights, lamps, switches outside – Lamps – High mounted stop lamp (HMSL) – To remove and fit** use the relevant sections to install the new assembly.

□

Note: When working to Repair Group 94 Lights, lamps, switches outside – Lamps – High mounted stop lamp (HMSL) – To remove and fit, the original assembly should be disposed of when removed, it is not necessary to conduct the disassembly process prior to disposal.

Identification

Upon completion apply a white campaign identification mark on the convertible roof mechanism - see Figure 1.




Figure 1

