

# SS: 1033422 TBB Fault 6485 Fault 6485 Aftertreatment 1 Diesel Exhaust Fluid pump

---

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue of Fault 6485 Aftertreatment 1 Diesel Exhaust Fluid pump Drive percentage-Data Erratic, intermittent, or incorrect

## Applicable Vehicles

C2/HDX/EFX

## Symptom

Fault Code 6485 turns Check engine light on, set fault 6485, or SPN 4375 FMI 2/2

## Solution:

refer to Cummins Trouble shooting, may access from Cummins Quick serve.  
Or Possible check the DEF Filter being damaged. Vender has improved the installation early March 2018, TBB working on supplying part number of the filter that can be ordered without replacing the complete header assembly

