

Date	Expiration	Release	Page
09.2018	09.2020	1	1(2)

First Release

2018-09-07

ACM & EMS SOFTWARE UPDATE

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, update EMS and ACM software to the latest version available. This update must be carried out by a qualified technician with a laptop having access to the Volvo systems. As soon as possible, make an appointment with your nearest Prevost Service Center or contact your service manager to carry out the update.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS		
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.		
Model	VIN	Fleet Number
X3-45 Commuter Model Year : 2015 - 2016	From 4RKG33497F9737001 up to 4RKG33491G9737299 incl.	From 2492 up to 2789, incl.
X3-45 Commuter Model Year : 2018	From 4RKJ33493J9737513 up to 4RKJ33498J9737541 incl.	From R802 up to R831, incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery.		

MATERIAL NEEDED

No material is required for this bulletin.

Date	Expiration	Release	Page
09.2018	09.2020	1	2(2)

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine.

1. Connect Premium Tech Tool (PTT) to the vehicle diagnostics connector (OBD). Connect the PC to a functional LAN or WiFi connection *and* a power source.
2. Turn the vehicle ignition switch to "ON". Activate hazards lights (4 way) to keep vehicle active.
3. Using PTT, update EMS and ACM software following the instructions provided in the Field Service Bulletins (FSB) below, available in Volvo Impact.

Engine emissions variant	Bulletin	Impact Identity
GHG14	FSB 284-068	142755330
OBD15	FSB 284-064	142066982
GHG17 and OBD18	FSB 284-069	142775412

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 30 minutes.

OTHER

VBC Bulletin	N/A
Fail Code	06.27-2
Defect Code	49
Syst. Cond	B
Causal Part	3092091

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>
 or scan the QR-Code with your smart phone.



Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.