

Measure no.

US 64332502-01

Subject

Keyless-Ride programming fails

Status date (mm/dd/yy)

7/13/18

Status

Approved

Organization

US, MOT

Date created (mm/dd/yy)

7/10/18

Created by

Markus Grosam

PQM Problem reference**Release date (mm/dd/yy)**

7/13/18

Approved by

Gery Torok

Dealer release

Allow automatic release

Vehicles affected**E series**

K48 K48/11 K48/12 K50 K50/11

Engine

K51 K52 K53 K54

Body**Production period (from/to)**

(mm/dd/yy)

/ 8/1/15

Comment on production period

with OE 0193 - Keyless Ride

Feedback (all cases relating to**measure up to) (mm/dd/yy)****Complaint**

When programming with ISTA, the update of the Keyless-Ride control module fails.

Cause

Program vehicle with Keyless-Ride and vehicle I level older than or equal to

K001-15-03-512

Measure

If possible, postpone software update

until this problem is rectified with a newer ISTA version

(expected in 08/2018 - ISTA 4.12.3x)

If the problem already exists, perform a IRAP/ remote session with:

remotesupport@bmw-motorrad.com.

Complaint**Fault location**66/12 Control module,
Keyless Ride**Fault type**

Programming abort

Fault place

Cause

#	Fault location	Fault type	Fault place
1	66/12 Control module, Keyless Ride		
Repair Task	Special Clearance	Area	
	No	Electrics/Electronics	

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
--------	-------	---------

© 2002-2018 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.