



# Preliminary Information

## PIP5525B 2016 2018 Chevrolet Spark TCM Replacement No Longer Needed During The Replacement Of A CVT7 Transmission

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Spark	2016 - 2018	All	All	All	MR8

Involved Region or Country	North America
Condition	TCM replacement is no longer needed when replacing a CVT7 transmission.
Cause	After following SI diagnostics, technicians may determine that the transmission needs to be replaced.

### Correction:

Please follow service information to aid in diagnosing CVT7 transmission concerns.

### Service Procedure:

Engineering no longer needs the TCM returned from vehicles needing transmission replacement.

### Version History

Version	3
Modified	Created on 9/26/2017 Updated on 5/16/2018 to add the 2018 Model Year and a note to only replace TCMs that have set codes and to not perform the Service Fast Learn Procedure with the original TCM installed in the vehicle. Updated on 9/11/2018 to end the request to replace the TCM during transmission replacement.



GENERAL MOTORS