

# Preliminary Information

## PIT5631 False DTC U0020 Setting in the Video Processing Control Module

### <u>Models</u>

| Brand:                     | Model:                     |   | Model Years: | VIN: |     | Engino: | Transmissions: |
|----------------------------|----------------------------|---|--------------|------|-----|---------|----------------|
| Di allu.                   |                            |   |              | from | to  | Engine: | Transmissions. |
| Chevrolet                  | Silverado 1500 (New Model) |   | 2019         | All  | All | All     | All            |
| GMC                        | Sierra 1500 (New Model)    |   | 2019         | All  | All | All     | All            |
| Involved Region or Country |                            | North America   |              |      |     |         |                |
| Additional Options (RPO)   |                            | UVI - Trailer Camera Package<br>or<br>UV2 - HD Surround Vision  |              |      |     |         |                |
| Condition                  |                            | It may be noticed when scanning the vehicle for DTC's there is a U0020 set current in the Video Processing Control Module (VPCM). |              |      |     |         |                |
| Cause                      |                            | The VPCM will set a false U0020 DTC as a result of a software anomaly.  |              |      |     |         |                |

#### Correction:

NONE. This is a false DTC and it should be ignored. The DTC does not cause any vehicle symptoms and does not indicate that there are any issues with the vehicle.

#### Note: This PI will be converted into a bulletin when new information is available.

#### Version History

| Version  | 1                    |
|----------|----------------------|
| Modified | 09/14/2018 - Created |



© 2018 General Motors. All Rights Reserved.