



# Preliminary Information

## PIT5632 Squeak, Rattle or Tick Noise From B-Pillar Area

Models

| Brand:    | Model:   | Model Years: | VIN: |     | Engine: | Transmissions: |
|-----------|----------|--------------|------|-----|---------|----------------|
|           |          |              | from | to  |         |                |
| Chevrolet | Colorado | 2018         | All  | All | All     | All            |
| GMC       | Canyon   | 2018         | All  | All | All     | All            |

|                                    |  |
|------------------------------------|--|
| <b>Involved Region or Country:</b> | <b>North America</b>   |
| <b>Additional RPO/s:</b>           | <b>None</b>  |
| <b>Condition:</b>                  | <b>Squeak , tick or rattle noise from the B-Pillar area.</b> |
| <b>Cause:</b>                      | <b>Metal to metal contact of the inner and outer panels.</b> |

**Correction:**

Engineering is investigating this concern. The root cause has been determined and best path to repair is being evaluated. Attemptno repair at this time . DO NOT put expanding foam in the pillar this will not repair the concern and will mak the eventual repair more difficult. This PI will be updated when the repair procedure has been established.

Version History

|          |                      |
|----------|----------------------|
| Version  | 1                    |
| Modified | 09/19/2018 - Created |

