

Discovery 17-18MY	Customers may report the hood will not open when pulling the release handle.	This may be caused by a hood latch release cable that is too long. A revised hood cable has been developed to address this concern that is 5.5 mm shorter in length. Should a customer express a concern, please refer to SSM73887 and replace the hood cable with the revised part. The concern is being reviewed for a possible proactive repair. Depending on the results of this decision the SSM will be replaced with either a Service Action or TSB.	SSM73887
----------------------	--	---	----------