

<p>Range Rover RR Sport 18MY</p>	<p>Customers may report that the second row seat folding feature is not operating as expected.</p>	<p>This may be caused by a seat memory control module software error. Should a customer express a concern, please refer to TSB LTB01203 and update the PSM, SCMC & SCMD software.</p>	<p>LTB01203NAS1</p>
--	--	---	---------------------