

Vehicle	Customer Concern	Details and Status	Publication
RR Sport SVR 18MY	Customers may report the finish on the hood is chipping around the vent inserts.	This may be caused by the ribs designed into the back of the plastic vent flange. Revised vents are being produced to address this concern. Should a customer express a concern, please submit an EPQR and await further instructions as to the repair of the vehicle.	TBC

